

**GOVERNMENT OF INDIA
AIRCRAFT ACCIDENT INVESTIGATION BUREAU
MINISTRY OF CIVIL AVIATION
SAFDARJUNG AIRPORT, NEW DELHI**

File No.:-11011/5/2018-AAIB

Date:- 14th Oct 2018.

ORDER –Accident

Whereas Boeing B737-800 aircraft VT-AYD, of M/s Air India Express, while operating schedule flight for sector Trichy- Dubai, met with an accident at Trichy on 12th of Oct 2018.

And, whereas it appears to the Aircraft Accident Investigation Bureau (AAIB), India that it is expedient to investigate and determine the probable cause(s) and contributory factor(s) leading to the accident and make recommendations to avoid reoccurrence of such accident in future.

Now, in exercise of the powers conferred by the Rule 11 (1) of the Aircraft (Accident and Incidents Investigation) Rules 2017, the Director General-AAIB, India hereby directs an Investigation of the said accident for the probable cause(s).

The Director General-AAIB, India is pleased to appoint Sh. Amit Gupta, Director, AED as Investigator – in – Charge. He will be assisted by the following investigator(s) to inquire into the circumstances of this accident.

1. Capt. Gaurav Pathak, Jet Airways.
2. Sh. Dinesh Kumar, Air Safety Officer, AAIB.

The Investigator-in-Charge will take the assistance of other experts/agencies whenever required.

The headquarters of the Investigation will be at New Delhi.

The Investigator-in-Charge will complete its inquiry and submit the report to AAIB, India, preferably within ten months from the date of issue of this order.



(Bir Singh Rai)
Director General
Aircraft Accident Investigation Bureau


बीर सिंह राय / BIR SINGH RAI
संयुक्त महानिदेशक / Joint Director General
विमान दुर्घटना अन्वेषण ब्यूरो
Aircraft Accident Investigation Bureau
भारत सरकार / Govt. of India
सफदरजंग हवाई अड्डा / Safdarjung Airport
नई दिल्ली-110003 / New Delhi-110003

File No. :- INV-11011/5/2018-AAIB

Date: 14th Oct 2018

Copy forwarded for information to:

1. Sh. Amit Gupta, Director, AED
2. Sh. Dinesh Kumar, Air Safety Officer, AAIB.
3. Capt. Gaurav Pathak, M/s Jet Airways.
4. DGCA, (Kind Attn: Sh. M J Singh, Director Air Safety)
5. Accountable Manager, M/s Air India Express.
6. PS to HMCA
7. PSO to Secretary
8. Sr.PPS to AS & FA
9. Sr.PS to JS (SKM)
10. PS to Dir (SN)
11. Sr. Tech Director NIC, MoCA
12. DG Section, MoCA.
13. IT Section, MoCA with the request to upload the Order on website of MoCA and AAIB
14. Guard Folder.



(K. Ramachandran)

Assistant Director

Aircraft Accident Investigation Bureau

के. रामाचन्द्रन / K. RAMACHANDRAN

सहा. निदेशक विमान सुरक्षा / Asst. Director Air Safety

विमान दुर्घटना अन्वेषण ब्यूरो

Aircraft Accident Investigation Bureau

भारत सरकार / Govt. of India

सफदरजंग हवाई अड्डा / Safdarjung Airport

नई दिल्ली-110003 / New Delhi-110003